



NEVADA DIVISION OF
**ENVIRONMENTAL
PROTECTION**

STATE OF NEVADA
Department of Conservation & Natural Resources
Brian Sandoval, Governor
Leo M. Drozdoff, P.E., Director
David Emme, Administrator

September 15, 2015

Mr. Cameron McKay
Kingsbury GID
PO BOX 2220
Stateline NV 89449

RECEIVED

SEP 18 2015

K.G.I.D.

Subject: SANITARY SURVEY OF KINGSBURY GID (NV0000004); DOUGLAS COUNTY

Dear Mr. McKay,

This letter serves to report the results of the Sanitary Survey inspection conducted by the Nevada Division of Environmental Protection, Bureau of Safe Drinking Water (BSDW), of the above referenced facility on **August 26, 2015**. The assistance of water system representatives mentioned below was very helpful and greatly appreciated.

Parties Present

| NAME | ORGANIZATION |
|-------------------|-------------------------------|
| Reginald Lang III | Bureau Of Safe Drinking Water |
| Eric Johnson | Kingsbury GID |

Significant Deficiencies

The following items are significant deficiencies which require immediate attention:
No observations were recorded in this category.

Other Deficiencies

The following items are deficiencies which require corrective action:
No observations were recorded in this category.

Observations/Recommendations

The following are observations, comments, and/or recommendations and require written response where indicated. The recommendations will enable your system to better conform to the requirements of applicable design criteria or other industry standards:

| FACILITY | CATEGORY | DESCRIPTION |
|--|------------------------|---|
| ST07 - STORAGE TANK 10 1MG 200K HEAVENLY | Finished Water Storage | Other issues or observations at finished water storage. |

Comments: Tank was recently rehabilitated and has developed a leak coming from the base area. The tank was drained and an attempt was made to patch the seams and penetrations in the base. The tank continues to leak.

| FACILITY | CATEGORY | DESCRIPTION |
|-------------------|-----------|--|
| TP02 - LAKE TAHOE | Treatment | Other issues or observations at treatment. |

| | | |
|--|--|--|
| SURFACE WATER PLANT STN 1 FIN | | |
| Comments: Vent screens for new finished water tank at new treatment plant appear to be too coarse. See Attachment #1 | | |

Monitoring and Reporting

Monitoring Violations:

No monitoring violations were reported in the past year.

Maximum Contaminant Level (MCL) Violations during the past year:

No maximum contaminant level violations were reported in the past year.

Other Violations during the past year:

No other violations were reported in the past year.

Positive bacteriological sampling history for the past year:

No Positive Samples were reported in the past year.

Reminders

The Nevada Administrative Code (NAC) 445A.6669 requires the Division’s approval prior to commencement of construction of any improvements, treatment process modifications, or the addition of new water sources.

The Nevada Administrative Code contains specific requirements for record keeping. Some records must be kept for as long as ten years. The Public Water System is responsible for maintaining its own records.

Most regulations, guidance documents, and forms are available via Internet on the Bureau’s website. Please link to www.ndep.nv.gov/bsdw for further information.

Additional information and guidance is available on the EPA's Office of Ground Water and Drinking Water web site (www.epa.gov/safewater) or at the Safe Drinking Water hotline (1-800-426-4791).

If you have any questions, please contact me at 775-687-9528. Thank you for your time and cooperation.


Sincerely,



Reginald Lang III, P.E. Staff III, Engineer
Bureau of Safe Drinking Water
rlang@ndep.nv.gov

cc: Andrea Seifert, P.E., PWS Compliance Branch Supervisor

Attachments



Attachment #1

Severity: Recommendations

Facility ID: LAKE TAHOE SURFACE WATER PLANT STN 1 FIN

Category: Treatment

Attachment Comments: Vent screen